### **Manhole Inspection Summary** Manhole # S17UU 004MH Printed On: 6/10/2009 Page 1 of 3 Inspection ✓ Is Incomplete Rating: Record Plat: 17UU Node: 004 Status: Not Found Insp Date: 3/5/09 9:31 AM Incomplete Comments Crew: ads4 Cannot Access - Buried - Manhole Existing Confirmed by Inspector: ADS2 **CCTV** Firm: ADS Location Address: 3120 REISTERSTOWN RD Cross Street: CHOWAN AVE Manhole Type: Location: Ground Conditions: Dry Weather: Dry Subject To Ponding: None Prev. Rehab Comments OPENED DS NODE 007 AND MEASURED 165.4 FEET TO LOCATION WHERE THIS NODE SHOULD BE. SEARCHED ALLEY WITH METAL DETECTOR WITHIN 10' RADIUS AND GOT NO POSITIVE RESULTS - IF IT STILL EXISTS IT IS BURRIED DEEP UNDER CONCRETE - CANNOT LOCATE. Diameter: (in.) Length: (in.) Dist A/B Grade: Cover Shape: (in.) Type: Sanitary Condition: Cover Material: Cast Iron Properties: Bolted Vented ☐ Water Tight ☐ Water Tight Insert Frame Offset: (in.) Condition: Sound Cracked Leaks **Chimney / Frame Adjustment** Exists Material: Parged Height: (in.) Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated Infiltration: \( \subseteq \text{None} \) ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall Corbel Material: Parged Type: Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated Infiltration: None Joint Cracks Mortar Roots Wall Barrel Material: Parged Shape: Diameter: (in.) Length: (in.) Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion Loose Brick Deteriorated Infiltration: None Joint Cracks Mortar Roots Wall **Bench** Exists Material: Parged Condition: Sound Cracked Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris Channel Material: ☐ Parged Channel Exposure: Fully Open Junc Dist: 0 nearest .5 ft. Azimuth:

☐ Deteriorated ☐ Leaks

(ft.) ☐ Active Surcharge Present

Debris

Condition: Sound Cracked Root Intrusion

☐ Evidence Of Surcharge

Missing:

Corroded

Depth:

Count:

**Steps** 

Surcharge

# **Manhole Inspection Summary**

## Manhole # S17UU\_004MH

Printed On: 6/10/2009 Page 2 of 3

# **Manhole Inspection Summary**

## Manhole # S17UU\_004MH

Printed On: 6/10/2009 Page 3 of 3